Bruhat Bangalore Mahanagara Palike

Inspection Report

1	Name of Work	Desilting of SWD at Muthyala nagara, Brundavana and HMT layout in JP Park
2	Administration Approval and Date	EE/RRND/AS/246/2011-12, Dated: 01-07-2011
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/246/2011-12, Dated: 01-07-2011
4	Estimate Amount	Rs. 10.00 lakhs
5	Job Code No	017-12-000001
6	P-Code	P0546
7	Agreement No & Date	EE/RRND/AGR/462/2012-13, dated: 27-11-2012
8	Work Order Number & Date	EE/RRND/Wo.No/462/2012-13, dated: 27-11-2012
9	Contract Amount as per Agreement	Rs. 10,48,925=00
10	Bill Amount	Rs. 10,48,925=00
11	B.R. No & Date	153/13-14 dated: 22-06-2013
12	Agency	V. Prakash
13	M.B. Number & Page No. of Measurement Recordes	Xerox copy of MB No. 81, Page No 8012 to 8013
14	Date of Inspection	11/10/2015
15	Enclusures	(1) Sketch showing the location of site (Area Map) (2) Four numbers of Photos taken during Inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned person. The work has been carried out more than two years back and the items involved in the above work are not accessible for measurements. As such the photos taken during the execution of the above work was scrutinized and Local enquiry has been made in this regard. It appears that the above work has been carried out. The same is referred to the Xerox copy of MB No 81

Received

EE(RRND) RR NAGARA
EXECUTIVE ENGINEER

11/10/2015
(R. SATHYANARAYANA)
INSPECTION REPORT OFFICER

Desilting of SWD at Muthyala nagara Basavanna and HMT layout in JP ward

Executive Engineer
Rajarajeshwarinagar Division
Bruhat Bangalore Mahanagara Palike
Bangalore

R. SATHYANARAYANA
INSPECTION OFFICER



Executive Engineer
Rajarajeshwari Nagar Division
Bruhat Bangalore Mahanagara Palike
Bangalore

R. SATHYANARAYANA
INSPECTION OFFICER